

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
All American Park	\$50,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Aloha Shores Park	\$83,000
01-Approach & Entrance	
Parking Lot - Shared with EOC Facility	
Exterior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Park Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$1,000
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls - Main	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
05-Sports Activity Area	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sports Area - Bocce	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
<hr/>	
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
<hr/>	
Sports Area - Roller Hockey	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
<hr/>	
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Angel Park	\$455,000
01-Approach & Entrance	
Main Entrance from Durango	
Curb Ramps	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$50,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$25,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$115,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$31,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$2,000
Restroom Amenities	
Deficient clear floor space for sink	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure restroom to allow for adequate clear floor space	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$1,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$1,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$2,000
Restroom - Women's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Deficient toilet stall dimensions	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure restroom stall to allowable dimension range	\$31,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$2,000
Restroom Amenities	
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$1,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$2,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Angel Park Trailhead	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ansan Sister City Park	\$188,000
01-Approach & Entrance	
Main Entrance from Parking Lot	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$50,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$12,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$1,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$35,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$15,000
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$15,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bettye Wilson Soccer Complex	\$10,000
08-Playgrounds	
Play Area - West	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bob Baskin Park	\$322,000
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$30,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$10,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
Restroom - Women's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$10,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
04-Additional Access	
Park Amenities	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bonanza/ Mojave Water Pollution Resource Center (WPCF)	\$23,000
01-Approach & Entrance	
West Entry	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
03-Restroom Facilities	
Restroom - Uni/Family - Interior	
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bradley Bridle Park (Equestrian Park)	\$72,000
01-Approach & Entrance	
Main Entrance	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$5,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$5,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
04-Additional Access	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Park Amenities	
Stairs	
Deficient handrail clearance	
Remount handrails to allowable clearance range	\$5,000
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$8,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bruce Trent Park (Angel Park)	\$608,500
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$60,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$25,000
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
Restroom - Women's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Public Restroom Approach	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$5,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
08-Playgrounds	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$30,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$20,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$30,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$40,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Buckskin Cliff Shadows Park/Trailhead	\$49,500
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Restroom - Women's Stalls -	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cameron Community Park	\$1,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Carson Parking Lot	\$6,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Centennial Hills Active Adult Center (CLV Portion)	\$1,000
02-Goods & Services	
Interior	
Interior Doors	
Deficient pounds per force to open interior doors - 18 lbF average	
Adjust door pounds per force or replace door closer	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Centennial Hills Park - Amphitheatre	\$35,000
01-Approach & Entrance	
Entrance	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Charleston Heights Park	\$412,000
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$5,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$75,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$20,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Charleston Neighborhood Presvn Park	\$50,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cimarron Rose Community Center	\$10,500
01-Approach & Entrance	
Main Entrance	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls - Indoor	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls - Indoor	
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cimarron Rose Park	\$81,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls - Main	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
City Centre Parking Garage	\$11,500
01-Approach & Entrance	
CLV Owned Ground Level (137 spaced avail)	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
City Hall	\$186,000
01-Approach & Entrance	
Main Entrance	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
02-Goods & Services	
Interior	
Elevators	
Deficient elevator call controls	
Repair or replace elevator controls	\$100,000
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$1,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000
03-Restroom Facilities	
Restroom - Men's Single - City Hall FI 3-7	
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom - Men's Stalls - CH Lobby Elevators	
Accessible Restroom Stall(s)	
Lacking stall grab bars	
Obtain and install grab bars	\$3,000
Accessible Urinals	
Deficient operable parts	
Repair or replace with ADA compliant operable parts	\$2,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Men's Stalls - Now Café/CH 2nd Floor	
Accessible Restroom Stall(s)	
Lacking stall grab bars	
Obtain and install grab bars	\$3,000
Accessible Urinals	
Deficient operable parts	
Repair or replace with ADA compliant operable parts	\$2,000
Restroom - Men's Stalls - Training Rooms	
Accessible Restroom Stall(s)	
Lacking stall grab bars	
Obtain and install grab bars	\$3,000
Accessible Urinals	
Deficient operable parts	
Repair or replace with ADA compliant operable parts	\$2,000
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$2,000
Restroom - Women's Single - City Hall Fl 3-7	
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom - Women's Stalls - CH Lobby Elevators	
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$2,000
Restroom - Women's Stalls - Now Café/CH 2nd Floor	
Accessible Restroom Stall(s)	
Lacking stall grab bars	
Obtain and install grab bars	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Women's Stalls - Training Rooms	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
City Hall Parking Garage	\$152,000
01-Approach & Entrance	
Parking Facility	
Entrance/Exterior Doors	
Deficient door hardware	
Repair or replace door hardware	\$1,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
02-Goods & Services	
Parking Facility	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Single - Parking Facility	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$10,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$10,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$40,000
Restroom - Women's Single - Parking Facility	
Public Restroom Approach	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$10,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$10,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$40,000
04-Additional Access	
Parking Facility	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Clarence Ray Memorial Park	\$167,500
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$40,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$30,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$20,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Coleman Park	\$215,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$55,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$50,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Container Park Parking Lot	\$1,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Derfelt Senior Center	\$128,000
01-Approach & Entrance	
Entrance	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
02-Goods & Services	
Interior	
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Single - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Uni/Family - Classroom 1	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Uni/Family - Classroom 2	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Single - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Toilet Rooms	
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$20,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain protrusion limits	
Replace or remount drinking fountain to proper height and depth	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Detention Center - Admin Building	\$139,500
01-Approach & Entrance	
Entrance	
Curb Ramps	
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$2,500
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$20,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$1,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$7,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ramps	
Deficient ramp handrails	
Reconfigure handrails to proper requirements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Detention Center - Correctional Facilities	\$201,500
01-Approach & Entrance	
Visitation/Bail Entrance	
Curb Ramps	
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$12,500
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$25,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$10,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$1,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Deficient loading zone access aisle	
Reconfigure and repaint loading zone access aisle	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$12,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Ramps	
Deficient ramp handrails	
Reconfigure handrails to proper requirements	\$15,000
02-Goods & Services	
Visitation/Bail Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$1,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000
Seating - General	
Reception area lacks accessible seating spaces	
Reconfigure reception area to accommodate accessible seating	\$1,000
04-Additional Access	
Visitation/Bail Additional Access	
Drinking Fountains	
Deficient drinking fountain protrusion limits	
Replace or remount drinking fountain to proper height and depth	\$5,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
12c-Detention & Correctional Facilities	
Detention & Correction Facilities	
Bathing Facility	
Bathing unit lacking grab bars	
Obtain and install grab bars	\$3,000
Inaccessible shower spray unit	
Obtain a shower hose to be available as an alternate to the shower spout which is a fixed pipe to the wall.	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Telephones	
Public phone instructions not provided in Braille	
Obtain and install proper signage	\$1,000
Public phone lacks proper accessible signage	
Obtain and install proper signage	\$1,000
Toilet Facility	
In accessible flush controls	
Replace/reposition flush controls to accessible location	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Development Services Center (Atrium Bldg.)	\$1,030,500
01-Approach & Entrance	
East Ground Entrance	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$10,000
Exterior door landing slope too steep	
Repair, bevel or ramp changes in level	\$20,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$3,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$15,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Parking Garage Exit Stairs	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$25,000
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$20,000
Deficient door hardware	
Repair or replace door hardware	\$4,000
Deficient door landing surface	
Repair or reconfigure door landing surface	\$20,000
West 3rd Floor Entrance & Above Grade Parking Garage	
Entrance/Exterior Doors	
Deficient door threshold	
Repair or replace door threshold	\$2,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$30,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$8,500
West Ground Entrance	
Entrance/Exterior Doors	
Deficient door threshold	
Repair or replace door threshold	\$2,500
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$15,000
02-Goods & Services	
1st Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$10,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
2nd Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
3rd Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
4th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
5th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
6th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
7th Floor	
Controls	
Deficient fire extinguisher height	
Relocate fire extinguisher to allowable height range	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
8th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
9th Floor	
Controls	
Deficient fire extinguisher height	
Relocate fire extinguisher to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
DSC Elevators	
Elevators	
Deficient elevator call controls	
Repair or replace elevator controls	\$100,000
Replace/reposition elevator car controls to accessible location/height range	\$50,000
Deficient elevator signage	
Repair or replace elevator signage	\$20,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000
Interior - DSC Room Signage Department & Tenant Signage	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
03-Restroom Facilities	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Men's Stalls - 1st Floor	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Accessible Urinals	
Deficient floor clear space	
Relocate urinal to allow for floor clear space	\$5,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 2nd Floor	
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$3,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 3rd Floor Central	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 3rd Floor West	
Public Restroom Approach	
Deficient restroom signage Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door closing speed Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 4th Floor	
Restroom Amenities	
Deficient knee clearance under sink Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 5th Floor	
Public Restroom Entrance	
Deficient door closing speed Adjust door closing speed or replace door closer	\$1,000
Deficient door threshold Repair or replace door threshold	\$3,000
Restroom Amenities	
Deficient knee clearance under sink Remount the counter element to allowable knee clearance	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 6th Floor	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 7th Floor	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 8th Floor	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
<hr/>	
Restroom - Men's Stalls - 9th Floor	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
<hr/>	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
<hr/>	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
<hr/>	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
<hr/>	
Restroom - Women's Stalls - 1st Floor	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$1,000
<hr/>	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
<hr/>	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
<hr/>	
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
<hr/>	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
<hr/>	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
<hr/>	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Restroom - Women's Stalls - 2nd Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 3rd Floor Central	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 3rd Floor West	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 4th Floor	
Restroom Amenities	
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 5th Floor	
Public Restroom Approach	
Deficient restroom signage Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient knee clearance under sink Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 6th Floor	
Public Restroom Approach	
Deficient restroom signage Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door closing speed Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 7th Floor	
Public Restroom Approach	
Deficient restroom signage Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 8th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 9th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
04-Additional Access	
Interior - DSC 1st Floor	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Telephones	
Deficient accessible telephone signage	
Obtain and install accessible telephone signage	\$5,000
Deficient telephone volume controls	
Replace with ADA compliant telephone	\$5,000
Deficient telephone with TTY capability	
Replace with ADA compliant telephone	\$5,000
Interior - DSC 1st Floor (applies to open stairway b/t 1st & 2nd floor)	
Stairs	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC 2nd - 9th Floor	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs - Stairs for the Bridge	
Stairs	
Deficient handrail clearance	
Remount handrails to allowable clearance range	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs - Stairs for the Open Stairway between garage levels 2 & 3	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Replace/ install ADA compliant handrails	\$2,500
<hr/>	
Interior - DSC Parking Garage & Bridge Exit Stairs Stairs for the Open Stairway between garage levels 3 & 4	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
<hr/>	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
<hr/>	
Interior - DSC Parking Garage & Bridge Exit Stairs Two Garage Exit Stairway Towers	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doolittle Pool	\$1,000
10-Swimming Pools	
Pool Area	
Accessible Pool Steps	
Deficient accessible step handrails	
Remount the handrail to the allowable ADA height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doolittle Senior Center	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls - NE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - SE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - NE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Downtown Parking Lot	\$14,000
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$12,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
DTC Parking Lot	\$6,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Dula Gymnasium Sports and Fitness Center	\$43,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$15,000
03-Restroom Facilities	
Restroom - Men's Locker -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Locker -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$5,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Durango Hills Park	\$47,000
01-Approach & Entrance	
Main	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$2,500
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Men's Stalls - Main	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$2,500
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$2,500
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Relocate restroom amenity to allowable reach range	\$2,000
<hr/>	
Restroom - Women's Stalls - Main	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$2,500
<hr/>	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
<hr/>	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
<hr/>	
04-Additional Access	
Park Amenities	
Stairs	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$8,500
<hr/>	
05-Sports Activity Area	
Sports Area - Basketball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
<hr/>	
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Durango Hills Water Resource Center (WPCF) - Admin	\$44,000
03-Restroom Facilities	
Restroom - Men's Stalls - South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Restroom - Women's Stalls - South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Las Vegas Community Center	\$26,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls - 1	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom - Men's Stalls - 2	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - 1	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - 2	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient knee clearance under drinking fountain	
Replace or remount drinking fountain to proper height and depth	\$3,500
06-Exercise Equipment	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fitness Area (both)	
Exercise Areas	
Inaccessible exercise equipment	
Reconfigure exercise equipment to allow for accessibility	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Yard - Facilities Mgmt./TEFO	\$26,000
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Yard - Vehicle Service - Bldg B	\$48,500
01-Approach & Entrance	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$15,000
Main Entrance	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Uni/Family -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ed Fountain Park	\$20,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Estelle Neal Park	\$30,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
04-Additional Access	
Park Interior	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ethel Pearson Park	\$215,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$10,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$15,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$15,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$25,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fifth Street School	\$28,000
01-Approach & Entrance	
Entrance - South side of bldg.	
Entrance/Exterior Doors	
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
02-Goods & Services	
Entrance - South side of bldg.	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls - Gallery	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - Gallery	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 001 / Central Fire Admin	\$240,500
01-Approach & Entrance	
Admin - Entrance West Side of Building	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$10,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Ramps	
Deficient ramp handrails	
Obtain and install handrails to proper requirements	\$10,000
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$7,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Admin - Interior	
Elevators	
Deficient elevator call controls	
Repair or replace elevator controls	\$50,000
Replace/reposition elevator car emergency communication	\$50,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Interior Doors	
Deficient door vision panel	
Repair or replace with door with vision panel	\$3,500
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000
Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$1,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$2,000
Deficient number of drinking fountains	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Install second accessible drinking fountain	\$30,000
Hazards & Emergency	
Deficient exit signage	
Obtain and install accessible exit signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 002	\$55,000
01-Approach & Entrance	
Entrance West Side of Building	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 003	\$77,000
01-Approach & Entrance	
Entrance North Side of Building	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door kick plate	
Install door kick plate	\$5,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$17,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Hazards & Emergency	
Deficient exit signage	
Obtain and install accessible exit signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 004	\$86,500
01-Approach & Entrance	
Entrance West Side of Building	
Curb Ramps	
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 005	\$25,500
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 006 (CSN)	\$1,500
01-Approach & Entrance	
Entrance East Side of Building	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 007	\$11,500
01-Approach & Entrance	
Entrance North Side of Building	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 008	\$5,000
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 009	\$90,500
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Hazards & Emergency	
Deficient exit signage	
Obtain and install accessible exit signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 010	\$66,500
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Uni/Family -	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 041	\$23,000
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 042	\$103,000
01-Approach & Entrance	
Entrance North Side of Building	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 043	\$44,500
01-Approach & Entrance	
Entrance South Side of the Building	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 044	\$22,000
01-Approach & Entrance	
Entrance North Side of Building	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 045	\$70,500
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 047	\$5,500
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 048	\$5,500
01-Approach & Entrance	
Entrance South Side of the Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 102 (Fire Training Center & Arson Investigations)	\$137,000
01-Approach & Entrance	
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient door kick plate	
Install door kick plate	\$5,000
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Relocate protruding obstacles or widen aisles	\$1,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$5,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$7,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
Hazards & Emergency	
Deficient fire alarm systems	
Obtain and install accessible fire alarm systems	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 106	\$31,500
01-Approach & Entrance	
Entrance West Side of Building	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
03-Restroom Facilities	
Restroom - Uni/Family -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 107	\$30,500
01-Approach & Entrance	
Entrance South Side of the Building	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 108	\$19,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fitzgerald Tot Lot Park	\$65,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area - Far South	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Floyd Lamb Park @ Tule Springs	\$1,172,000
01-Approach & Entrance	
Guard Shack Parking Lot	
Curb Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Historic Area Parking Lot - South	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Historic Area Parking Lot - West	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Horse for Heros Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$20,000
Parking Lot #2 - Restroom	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$15,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Parking Lot #3	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Deficient loading zone access aisle	
Reconfigure and repaint loading zone access aisle	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$25,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Parking Lot #3 - Restroom	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable dimensions	\$40,000
Deficient ramp handrails	
Install edge protection or extend ground surface	\$5,000
Parking Lot #4	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Parking Lot #5	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior - Historic Area	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Park Interior - Pond Area	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000
03-Restroom Facilities	
Restroom - Uni/Family -	
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000
Restroom - Uni/Family - #2	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet stall dimensions	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Uni/Family - #3	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Restroom - Uni/Family - #4	
Public Restroom Approach	
Deficient restroom signage	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$5,000
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$5,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Restroom - Uni/Family - #5	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$5,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Install second accessible drinking fountain	\$65,000
05-Sports Activity Area	
Sports Area -Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Freedom Pool (CMDH Family Pool)	\$43,000
01-Approach & Entrance	
Main Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking protective white sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Restroom - Uni/Family -	
Restroom Amenities	
Lacking protective white sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking protective white sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
10-Swimming Pools	
Pool Area	
Accessible Pool Steps	
Lacks second handrail	
Install second entry handrail to accessible steps	\$5,000
Sloped Entry	
Lacks second handrail	
Install second entry handrail to accessible steps	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Garehime Heights Park	\$61,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Ramps	
Deficient ramp handrails	
Install edge protection or extend ground surface	\$5,000
Reconfigure handrails to proper requirements	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Garside Pool	\$20,000
01-Approach & Entrance	
Main Entrance	
Ramps	
Deficient ramp handrails	
Install edge protection or extend ground surface	\$5,000
02-Goods & Services	
Pool Area	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls - Outdoor	
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Toilet Rooms	
Deficient pounds per force flush controls	
Adjust flush control pounds per force or replace flush controls	\$1,000
Restroom - Women's Stalls - Outdoor	
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Toilet Rooms	
Deficient pounds per force flush controls	
Adjust flush control pounds per force or replace flush controls	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gary Dexter Park	\$10,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gilcrease Brothers Park	\$79,000
01-Approach & Entrance	
Main	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$10,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$10,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
05-Sports Activity Area	
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gilmore Cliff Shadows Trailhead	\$5,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gold Spike Parking Lot	\$6,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Heers Park	\$20,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Heritage Park	\$215,000
01-Approach & Entrance	
Main	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$40,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$40,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Restroom - Women's Stalls -	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$5,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$15,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Hualapai Canyon Trailhead	\$46,500
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Huntridge Circle Park	\$84,500
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Insulate exposed pipes	\$1,000
<hr/>	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
<hr/>	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lieburn Senior Center	\$4,000
02-Goods & Services	
Interior	
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$1,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Llama Parking Lot	\$5,000
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lorenzi Park	\$50,000
08-Playgrounds	
Play Area - NE Middle	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Play Area - NW 5-12 yrs	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$20,000
Play Area - SE 5-12 yrs	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lorenzi Park - Sammy Davis JR Festival Plaza	\$10,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lubertha Johnson Park	\$220,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$10,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Toilet Rooms	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$10,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Toilet Rooms	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$3,000
Play Area - Far North	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$21,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$9,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$27,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$12,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$9,000
Play Areas	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$9,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$27,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Matlock Parking Lot	\$11,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Minker Sports Center	\$569,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$7,500
Interior Doors	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$10,000
Restroom Amenities	
Lacking white protective sleeve	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Insulate exposed pipes	\$1,000
Mirror edge too high Remount mirror to allowable height range	\$1,000
Shower Facilities	
Deficient operable parts Repair or replace with ADA compliant operable parts	\$5,000
Deficient shower configuration Reconfigure shower for ADA accessibility	\$95,000
Toilet Rooms	
Deficient grab bars Obtain and install accessible grab bars	\$3,500
Deficient toilet stall dimensions Reconfigure restroom stall to allowable dimension range	\$75,000
Grab bar is not within allowable height range Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls - Accessible Restroom Stall(s)	
Deficient toilet stall dimensions Reconfigure restroom stall to allowable dimension range	\$75,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors Adjust door pounds per force or replace door closer	\$10,000
Restroom Amenities	
Lacking white protective sleeve Insulate exposed pipes	\$1,000
Mirror edge too high Remount mirror to allowable height range	\$1,000
Shower Facilities	
Deficient operable parts Repair or replace with ADA compliant operable parts	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient shower configuration	
Reconfigure shower for ADA accessibility	\$95,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirabelli Community Center	\$7,500
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls - NW	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirabelli Park	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Municipal Pool	\$23,000
02-Goods & Services	
Interior	
Interior Doors	
Deficient door vision panel	
Repair or replace with door with vision panel	\$10,000
03-Restroom Facilities	
Restroom - Men's Locker - Exit Door to Pool	
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door closing speed or replace door closer	\$1,000
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls - Exit Door to Pool	
Public Restroom Entrance	
Deficient pounds per force to open restroom doors	
Adjust door pounds per force or replace door closer	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Neonopolis Garage Parking	\$10,000
01-Approach & Entrance	
Parking Facility	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Patriot Community Park	\$24,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Pavilion Center Pool	\$15,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Interior Doors	
Deficient door vision panel	
Repair or replace with door with vision panel	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Pioneer Park	\$45,000
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
05-Sports Activity Area	
Sports Area - Bocce	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Police Memorial Park	\$251,000
01-Approach & Entrance	
North Parking Lot	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$25,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$10,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
South Parking Lot	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$25,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$10,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Repair, bevel or ramp changes in level	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$2,500
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Restroom Amenities	
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$2,500
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
05-Sports Activity Area	
Sports Area - Basketball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Paddle Ball	
Sports Activity Areas	
Deficient Access Routes	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure/repair accessible route	\$10,000
<hr/>	
Sports Area - Skate Park	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
<hr/>	
Sports Area - Tennis	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
<hr/>	
08-Playgrounds	
Play Area age 2-5	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
<hr/>	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000
<hr/>	
Play Area age 5-12	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
<hr/>	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
<hr/>	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Polly Gonzalez Memorial Park	\$15,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Rainbow Family Park	\$30,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Rotary Park	\$25,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sky Ridge Park	\$40,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stewart Place Park	\$175,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$10,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stupak Community Center	\$28,000
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
02-Goods & Services	
Interior	
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
06-Exercise Equipment	
Fitness Area	
Exercise Areas	
Inaccessible exercise equipment	
Reconfigure exercise equipment to allow for accessibility	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sunny Springs Park	\$49,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Symphony Park Parking Lot	\$1,500
01-Approach & Entrance	
Open Surface Lot	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Thunderbird - Raptor Play Park	\$51,000
01-Approach & Entrance	
Main	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$4,000
Remount restroom signage to proper height	\$2,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$2,000
Lacking white protective sleeve	
Insulate exposed pipes	\$2,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Thunderbird Family Sports Complex (Lacrosse Fields)	\$10,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Traffic Signal Shop - 20 Shop	\$24,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain protrusion limits	
Replace or remount drinking fountain to proper height and depth	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Veterans Memorial Leisure Service Center	\$89,000
01-Approach & Entrance	
Entrance	
Curb Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$1,000
Interior Doors	
Deficient pounds per force to open interior doors	
Adjust door pounds per force or replace door closer	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls - North	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Men's Stalls - South	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Shower Facilities	
Deficient shower controls height	
Repair or replace shower control location to allowable height range	\$5,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Uni/Family - Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom - Women's Stalls - North Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls - South Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Shower Facilities	
Deficient shower controls height	
Repair or replace shower control location to allowable height range	\$5,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
06-Exercise Equipment	
Fitness Area	
Exercise Areas	
Inaccessible exercise equipment	
Reconfigure exercise equipment to allow for accessibility	\$12,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
W. Wayne Bunker Family Park	\$241,500
01-Approach & Entrance	
Alexander Parking Lot - East	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Alexander Parking Lot - West	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Tenaya Parking Lot	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$5,000
Restroom - Women's Stalls -	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$5,000
05-Sports Activity Area	
Sports Area - Sand Volleyball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area #1 (most west)	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000
Play Area #2 Mid	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$5,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$5,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$5,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$25,000
Play Area #3 (far East)	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Water Pollution Control Facility	\$64,500
01-Approach & Entrance	
Main Entry East - Warehouse	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Main Entry North - Lab	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Main Entry South - Ops & Maint.	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Main Entry West - Admin	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls - Admin	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - Lab Main North	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Men's Stalls - Ops & Maint Main South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Restroom - Women's Stalls - Admin	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - Lab Main North	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Restroom - Women's Stalls - Ops & Maint Main South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Women's Stalls - Warehouse	
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Charleston Lions/Essex Park	\$95,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$5,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$5,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Emergency Operations Center	\$25,500
01-Approach & Entrance	
Entrance MAIN Double Door	
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Field Operation/ Maintenance	\$63,500
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$45,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$15,000
03-Restroom Facilities	
Restroom - Men's Stalls - Front	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
Restroom - Women's Stalls - Front	
Public Restroom Entrance	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Vehicle Services	\$82,000
01-Approach & Entrance	
Main Entrance	
Entrance/Exterior Doors	
Deficient door closing speed	
Adjust door closing speed or replace door closer	\$1,000
02-Goods & Services	
Main Entrance	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$20,000
Service counter is not within allowable length.	
Remount or replace with ADA compliant service counter	\$5,000
03-Restroom Facilities	
Restroom - Uni/Family -	
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$50,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Wildwood Park	\$25,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$5,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Winding Trails Park	\$46,500
01-Approach & Entrance	
Main	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$25,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$2,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls -	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls -	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Woofter Family Park	\$228,500
01-Approach & Entrance	
Main	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$40,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$45,000
03-Restroom Facilities	
Restroom - Men's Stalls -	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls - Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$15,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$5,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$5,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000