

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
All American Park	\$58,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure or replace playground equipment	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Aloha Shores Park	\$89,000
01-Approach & Entrance	
Parking Lot - Shared with EOC Facility	
Exterior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$1,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Park Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$1,000
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Accessible Urinals	
Deficient urinal dimensions	
Relocate urinal to allowable ADA dimensions	\$5,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
04-Additional Access	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
05-Sports Activity Area	
Sports Area - Bocce	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Roller Hockey	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Angel Park	\$483,000
01-Approach & Entrance	
Main Entrance from Durango	
Curb Ramps	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$50,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$25,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$115,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$41,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$6,000
Remount restroom signage to proper height	\$3,000
Restroom Amenities	
Coat hooks too high	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$1,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$1,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$2,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Deficient toilet stall dimensions	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure restroom stall to allowable dimension range	\$41,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$6,000
Remount restroom signage to proper height	\$3,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$1,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$2,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Angel Park Trailhead	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Betty Wilson Soccer Complex	\$69,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls - East	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls - West	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Lacking white protective sleeve	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Insulate exposed pipes	\$1,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area - West	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bob Baskin Park	\$350,000
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$60,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$10,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
Restroom - Women's Stalls - Main	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$5,000
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$10,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
05-Sports Activity Area	
Sports Area	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bonanza/ Mojave Water Pollution Resource Center (WPCF)	\$23,000
01-Approach & Entrance	
West Entry	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
03-Restroom Facilities	
Restroom - Unisex Single - Interior	
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bradley Bridle Park (Equestrian Park)	\$67,000
01-Approach & Entrance	
Main Entrance	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$5,000
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$5,000
04-Additional Access	
Park Amenities	
Stairs	
Deficient handrail clearance	
Remount handrails to allowable clearance range	\$5,000
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$8,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Buckskin Cliff Shadows Park/Trailhead	\$48,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Restroom - Women's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cameron Community Park	\$1,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Centennial Hills Park - Amphitheatre	\$35,000
01-Approach & Entrance	
Entrance	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Charleston Heights Park	\$501,000
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient accessible route	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$5,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$150,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$20,000
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$10,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient entrance floor surface slope Repair, bevel or ramp changes in level	\$20,000
Restroom Amenities	
Counter is not within allowable height range Remount the counter element to allowable height range	\$10,000
Lacking white protective sleeve Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet location Remount toilet to allowable centerline range	\$20,000
Grab bar is not within allowable height range Remount the handrail within proper height range	\$3,500
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains Install second accessible drinking fountain	\$15,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components Replace/reconfigure/repair elevated play components	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Charleston Neighborhood Presvn Park	\$50,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cimarron Rose Community Center	\$9,500
01-Approach & Entrance	
Main Entrance	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls - Indoor	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls - Indoor	
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Cimarron Rose Park	\$81,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
City Hall	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - CH Lobby Elevators	
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom - Women's Stalls - CH Lobby Elevators	
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
City Hall Parking Garage	\$147,000
01-Approach & Entrance	
Parking Facility	
Entrance/Exterior Doors	
Deficient door hardware	
Repair or replace door hardware	\$1,000
02-Goods & Services	
Parking Facility	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Single - Parking Facility	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$10,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$10,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$40,000
Restroom - Women's Single - Parking Facility	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$10,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$10,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$40,000
04-Additional Access	
Parking Facility	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Clarence Ray Memorial Park	\$167,500
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$40,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$30,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$20,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Coleman Park	\$215,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$55,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$50,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Derfelt Senior Center	\$113,000
01-Approach & Entrance	
Entrance	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Single - Main	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$20,000
Restroom - Unisex Single - Classroom 1	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Unisex Single - Classroom 2	
Restroom Amenities	
Lacking white protective sleeve	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Single - Main	
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$20,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain protrusion limits	
Replace or remount drinking fountain to proper height and depth	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Development Services Center (Atrium Bldg.)	\$951,000
01-Approach & Entrance	
East Ground Entrance	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$10,000
Exterior door landing slope too steep	
Repair, bevel or ramp changes in level	\$20,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$3,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$15,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking Garage Exit Stairs	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$25,000
Deficient door hardware	
Repair or replace door hardware	\$4,000
Deficient door landing surface	
Repair or reconfigure door landing surface	\$20,000
West 3rd Floor Entrance & Above Grade Parking Garage	
Entrance/Exterior Doors	
Deficient door threshold	
Repair or replace door threshold	\$2,500
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
Exterior Accessible Route	
Abrupt surface changes are present	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Repair, bevel or ramp changes in level	\$5,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$30,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$8,500
West Ground Entrance	
Entrance/Exterior Doors	
Deficient door threshold	
Repair or replace door threshold	\$2,500
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Holes/cracks in ground exceed 1/2 inches	
Repair or reconfigure ground surface	\$15,000
02-Goods & Services	
1st Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$10,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
2nd Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
3rd Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
4th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
5th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$20,000
6th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
7th Floor	
Controls	
Deficient fire extinguisher height	
Relocate fire extinguisher to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
8th Floor	
Controls	
Deficient light control height	
Relocate light control to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
9th Floor	
Controls	
Deficient fire extinguisher height	
Relocate fire extinguisher to allowable height range	\$5,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Interior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
DSC Elevators	
Elevators	
Deficient elevator call controls	
Repair or replace elevator controls	\$100,000
Replace/reposition elevator car controls to accessible location/height range	\$50,000
Deficient elevator signage	
Repair or replace elevator signage	\$20,000
Signage	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000
Interior - DSC Room Signage Department & Tenant Signage	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
03-Restroom Facilities	
Restroom - Men's Stalls - 1st Floor	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Accessible Urinals	
Deficient floor clear space	
Relocate urinal to allow for floor clear space	\$5,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 2nd Floor	
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$3,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Men's Stalls - 3rd Floor Central	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 3rd Floor West	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 4th Floor	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 5th Floor	
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$3,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 6th Floor	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 7th Floor	
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 8th Floor	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Men's Stalls - 9th Floor	
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 1st Floor	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions Reconfigure restroom stall to allowable dimension range	\$1,000
Stall door lacks pulls on both sides of door Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Coat hooks too high Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity maneuvering clearance Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Toilet Rooms	
Deficient toilet location Remount toilet to allowable centerline range	\$20,000
Restroom - Women's Stalls - 2nd Floor	
Public Restroom Approach	
Deficient restroom signage Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient restroom amenity pounds per force Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 3rd Floor Central	
Public Restroom Approach	
Deficient restroom signage Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 3rd Floor West	
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 4th Floor	
Restroom Amenities	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 5th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 6th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 7th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 8th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
Restroom - Women's Stalls - 9th Floor	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient knee clearance under sink	
Remount the counter element to allowable knee clearance	\$5,000
Deficient restroom amenity pounds per force	
Replace with ADA compliant restroom amenity	\$1,000
04-Additional Access	
Interior - DSC 1st Floor	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Telephones	
Deficient accessible telephone signage	
Obtain and install accessible telephone signage	\$5,000
Deficient telephone volume controls	
Replace with ADA compliant telephone	\$5,000
Deficient telephone with TTY capability	
Replace with ADA compliant telephone	\$5,000
Interior - DSC 1st Floor (applies to open stairway b/t 1st & 2nd floor)	
Stairs	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC 2nd - 9th Floor	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs - Stairs for the Bridge	
Stairs	
Deficient handrail clearance	
Remount handrails to allowable clearance range	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs - Stairs for the Open Stairway between garage levels 2 & 3	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs Stairs for the Open Stairway between garage levels 3 & 4	
Stairs	
Deficient handrail height	
Remount handrails to allowable height range	\$2,500
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500
Interior - DSC Parking Garage & Bridge Exit Stairs Two Garage Exit Stairway Towers	
Stairs	
Deficient handrails extension	
Replace/ install ADA compliant handrails	\$2,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doolittle Pool	\$1,000
10-Swimming Pools	
Pool Area	
Accessible Pool Steps	
Deficient accessible step handrails	
Remount the handrail to the allowable ADA height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doolittle Senior Center	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls - NE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - SE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - NE	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Dula Gymnasium Sports and Fitness Center	\$28,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Locker	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Locker	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$5,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Durango Hills Water Resource Center (WPCF) - Admin	\$44,000
03-Restroom Facilities	
Restroom - Men's Stalls - South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Restroom - Women's Stalls - South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Las Vegas Community Center	\$40,000
01-Approach & Entrance	
Entrance	
Entrance/Exterior Doors	
Exterior door landing slope too steep	
Repair, bevel or ramp changes in level	\$20,000
Exterior Ramp - North Side Exit	
Ramps	
Deficient Ramp Landing	
Repair or replace ramp landing to allowable slope	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Yard - Facilities Mgmt./TEFO	\$24,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
East Yard - Vehicle Service - Bldg B	\$46,500
01-Approach & Entrance	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$15,000
Main Entrance	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Install accessible signs at spaces lacking signage	\$1,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ed Fountain Park	\$24,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom - Women's Stalls - East	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom - Women's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Estelle Neal Park	\$28,000
03-Restroom Facilities	
Restroom - Men's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls - Main	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
04-Additional Access	
Park Interior	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ethel Pearson Park	\$215,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$10,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$15,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$15,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$25,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 001 / Central Fire Admin	\$180,500
01-Approach & Entrance	
Admin - Entrance West Side of Building	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$10,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Ramps	
Deficient ramp handrails	
Obtain and install handrails to proper requirements	\$10,000
Entrance East Side of Building	
Entrance/Exterior Doors	
Deficient exterior entrance signage	
Install exterior directional signage	\$1,000
02-Goods & Services	
Admin - Interior	
Elevators	
Deficient elevator call controls	
Repair or replace elevator controls	\$50,000
Replace/reposition elevator car emergency communication	\$50,000
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Interior Doors	
Deficient door vision panel	
Repair or replace with door with vision panel	\$3,500
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$1,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Hazards & Emergency	
Deficient exit signage	
Obtain and install accessible exit signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 002	\$11,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 003	\$75,500
01-Approach & Entrance	
Entrance North Side of Building	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Deficient door kick plate	
Install door kick plate	\$5,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$17,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000
04-Additional Access	
Additional Access	
Hazards & Emergency	
Deficient exit signage	
Obtain and install accessible exit signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 004	\$29,000
01-Approach & Entrance	
Entrance West Side of Building	
Curb Ramps	
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$6,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 005	\$23,000
01-Approach & Entrance	
Entrance East Side of Building	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 007	\$5,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 009	\$5,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 010	\$6,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Unisex Single	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 041	\$5,500
01-Approach & Entrance	
Entrance East Side of Building	
Parking	
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 042	\$53,000
01-Approach & Entrance	
Entrance North Side of Building	
Entrance/Exterior Doors	
Deficient door kick plate	
Install door kick plate	\$5,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 043	\$28,000
01-Approach & Entrance	
Entrance South Side of the Building	
Entrance/Exterior Doors	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 044	\$3,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 045	\$33,000
01-Approach & Entrance	
Entrance East Side of Building	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 047	\$3,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 048	\$3,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 106	\$4,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000
03-Restroom Facilities	
Restroom - Unisex Single	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 107	\$3,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fire Station 108	\$3,000
02-Goods & Services	
Interior	
Interior Accessible Route	
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Fitzgerald Tot Lot Park	\$50,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area - Far South	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Floyd Lamb Park @ Tule Springs	\$1,155,500
01-Approach & Entrance	
Guard Shack Parking Lot	
Curb Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$20,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$6,000
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Historic Area Parking Lot - South	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Missing or faded access aisle markings Reconfigure/repaint accessible/van accessible spaces	\$2,500
Historic Area Parking Lot - West	
Parking	
Lacking proper # of HC/Van Access spaces Reconfigure/repaint accessible/van accessible spaces	\$10,000
Missing or faded access aisle markings Reconfigure/repaint accessible/van accessible spaces	\$2,500
Horse for Heros Entrance	
Parking	
Lacking proper # of HC/Van Access spaces Reconfigure/repaint accessible/van accessible spaces	\$20,000
Parking Lot #2 - Restroom	
Exterior Accessible Route	
Abrupt surface changes are present Repair, bevel or ramp changes in level	\$6,000
Parking	
Access aisles not properly located/identified Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces Reconfigure/repaint accessible/van accessible spaces	\$15,000
Lacking proper HC signage/height/content Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings Reconfigure/repaint accessible/van accessible spaces	\$2,500
Parking Lot #3	
Exterior Accessible Route	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Deficient loading zone access aisle	
Reconfigure and repaint loading zone access aisle	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$25,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Remount accessible signage to allowable range (raise or lower signs) and install standard signs at spaces lacking proper signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
No van accessible space to measure	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Parking Lot #3 - Restroom	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Ramps	
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable dimensions	\$40,000
Deficient ramp handrails	
Install edge protection or extend ground surface	\$5,000
Parking Lot #4	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$3,000
Parking Lot #5	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Park Interior - Historic Area	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000
Park Interior - Pond Area	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000
03-Restroom Facilities	
Restroom - Unisex Single - #2	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Entrance	
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Unisex Single - #3	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Restroom - Unisex Single - #4	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient entrance floor surface slope	
Repair, bevel or ramp changes in level	\$5,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$5,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Restroom - Unisex Single - #5	
Public Restroom Approach	
Deficient restroom signage	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Obtain and install proper signage	\$1,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet seat height	
Remount toilet seat to allowable height range	\$5,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$20,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Unisex Single - #1	
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$65,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
05-Sports Activity Area	
Sports Area -Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Garehime Heights Park	\$58,000
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Ramps	
Deficient ramp handrails	
Install edge protection or extend ground surface	\$5,000
Reconfigure handrails to proper requirements	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Garside Pool	\$2,000
03-Restroom Facilities	
Restroom - Men's Stalls - Outdoor	
Toilet Rooms	
Deficient pounds per force flush controls	
Adjust flush control pounds per force or replace flush controls	\$1,000
Restroom - Women's Stalls - Outdoor	
Toilet Rooms	
Deficient pounds per force flush controls	
Adjust flush control pounds per force or replace flush controls	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gary Dexter Park	\$10,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gilcrease Brothers Park	\$75,500
01-Approach & Entrance	
Main	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$10,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$10,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
05-Sports Activity Area	
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$20,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Gilmore Cliff Shadows Trailhead	\$4,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Heers Park	\$33,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Heritage Park	\$213,000
01-Approach & Entrance	
Main	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$40,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$40,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Restroom - Women's Stalls	
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$5,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$15,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Hualapai Canyon Trailhead	\$45,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$15,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Huntridge Circle Park	\$81,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$10,000
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Kellogg-Zaher Sports Complex	\$6,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lieburn Senior Center	\$3,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lorenzi Park	\$92,000
03-Restroom Facilities	
Restroom - Men's Stalls - Ballfields	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls - Ballfields	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
08-Playgrounds	
Play Area - NE Middle	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Play Area - NW 5-12 yrs	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$20,000
Play Area - SE 5-12 yrs	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lorenzi Park - Sammy Davis JR Festival Plaza	\$10,000
02-Goods & Services	
Interior	
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Lubertha Johnson Park	\$217,000
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$10,000
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Toilet Rooms	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Toilet Rooms	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$10,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$3,000
Play Area - Far North	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$21,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$9,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$27,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$12,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$9,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$9,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$27,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Minker Sports Center	\$543,000
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
02-Goods & Services	
Interior	
Benches	
Reception benches do not have back support	
Repair or replace with ADA compliant bench	\$7,500
Interior Doors	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Signage	
Deficient interior permanent room/Exit signage	
Repair, relocate or replace interior permanent room/Exit signage	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Shower Facilities	
Deficient operable parts	
Repair or replace with ADA compliant operable parts	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient shower configuration	
Reconfigure shower for ADA accessibility	\$95,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Shower Facilities	
Deficient operable parts	
Repair or replace with ADA compliant operable parts	\$5,000
Deficient shower configuration	
Reconfigure shower for ADA accessibility	\$95,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$3,500

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirabelli Community Center	\$6,000
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$5,000
03-Restroom Facilities	
Restroom - Men's Stalls - NW	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirabelli Park	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Patriot Community Park	\$22,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Pavilion Center Pool	\$15,500
01-Approach & Entrance	
Entrance	
Parking	
Lacking proper HC signage/height/content	
Install accessible van signage at spaces lacking sign	\$1,500
02-Goods & Services	
Interior	
Interior Doors	
Deficient door vision panel	
Repair or replace with door with vision panel	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Pioneer Park	\$51,500
01-Approach & Entrance	
Main	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Missing or faded access aisle markings	
Reconfigure/repaint accessible/van accessible spaces	\$2,500
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$2,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$2,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
05-Sports Activity Area	
Sports Area - Bocce	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Horseshoes	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
08-Playgrounds	
Play Area	
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Police Memorial Park	\$136,000
01-Approach & Entrance	
North Parking Lot	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$10,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$25,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$2,500
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient clear floor space for sink	
Reconfigure restroom to allow for adequate clear floor space	\$2,500
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
05-Sports Activity Area	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sports Area - Basketball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Paddle Ball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Skate Park	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
Sports Area - Tennis	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
08-Playgrounds	
Play Area age 2-5	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000
Play Area age 5-12	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Rainbow Family Park	\$80,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Remount grab bar to allowable ADA dimensions/ wall distance	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Remount grab bar to allowable ADA dimensions/ wall distance	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Restroom Amenities	
Coat hooks too high	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Remount coat hooks to allowable height range	\$1,000
<hr/>	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
<hr/>	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
<hr/>	
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$3,500
<hr/>	
Restroom - Men's Stalls - Ballfields	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
<hr/>	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
<hr/>	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
<hr/>	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
<hr/>	
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
<hr/>	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
<hr/>	
Restroom - Women's Stalls - Ballfields	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
<hr/>	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
<hr/>	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
08-Playgrounds	
Play Area	
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sky Ridge Park	\$40,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stewart Place Park	\$175,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$40,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$10,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Reconfigure accessible maneuvering clearance around play area elements	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Stupak Community Center	\$18,000
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$5,000
Parking	
Access aisles not properly located/identified	
Mount compliant signage for access aisles	\$10,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
06-Exercise Equipment	
Fitness Area	
Exercise Areas	
Inaccessible exercise equipment	
Reconfigure exercise equipment to allow for accessibility	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Sunny Springs Park	\$46,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
08-Playgrounds	
Play Area	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$10,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Thunderbird - Raptor Play Park	\$48,000
01-Approach & Entrance	
Main	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$4,000
Remount restroom signage to proper height	\$2,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$2,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$4,000
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Traffic Signal Shop - 20 Shop	\$22,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$5,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
04-Additional Access	
Additional Access	
Drinking Fountains	
Deficient drinking fountain protrusion limits	
Replace or remount drinking fountain to proper height and depth	\$1,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Veterans Memorial Leisure Service Center	\$96,500
01-Approach & Entrance	
Entrance	
Parking	
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
02-Goods & Services	
Interior	
Seating - Assembly Areas	
Deficient accessible spaces ajoined by accessible routes	
Replace 4 existing bleacher seating units with accessible options	\$5,000
Deficient companion seating alignment	
Replace 4 existing bleacher seating units with accessible options	\$5,000
Deficient number of wheelchair spaces provided and lacking integration	
Replace 4 existing bleacher seating units with accessible options	\$10,000
Deficient vertical and horizontal wheelchair spaces disperment	
Replace 4 existing bleacher seating units with accessible options	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls - North	
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$5,000
Restroom - Men's Stalls - South	
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$15,000
Restroom - Women's Stalls - South	
Restroom Amenities	
Counter is not within allowable height range	
Remount the counter element to allowable height range	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
W. Wayne Bunker Family Park	\$235,000
01-Approach & Entrance	
Alexander Parking Lot - East	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$20,000
Tenaya Parking Lot	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Women's Stalls	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$5,000
05-Sports Activity Area	
Sports Area - Sand Volleyball	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$10,000
08-Playgrounds	
Play Area #1 (most west)	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000
Play Area #2 Mid	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$10,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$5,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$5,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$25,000
Play Area #3 (far East)	
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$5,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Water Pollution Control Facility	\$64,500
01-Approach & Entrance	
Main Entry East - Warehouse	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Main Entry North - Lab	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
Main Entry South - Ops & Maint.	
Parking	
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Main Entry West - Admin	
Parking	
Lacking proper HC signage/height/content	
Repair, remount or replace HC parking signage	\$1,500
03-Restroom Facilities	
Restroom - Men's Stalls - Admin	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - Lab Main North	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Men's Stalls - Ops & Maint Main South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Restroom - Women's Stalls - Admin	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - Lab Main North	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Remount restroom signage to proper height	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000
Restroom - Women's Stalls - Ops & Maint Main South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient toilet location	
Remount toilet to allowable centerline range	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom - Women's Stalls - Warehouse	
Restroom Amenities	
Mirror edge too high	
Remount mirror to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Charleston Lions/Essex Park	\$95,000
01-Approach & Entrance	
Main	
Exterior Accessible Route	
Deficient accessible route	
Reconfigure/repair accessible route	\$20,000
Repair, bevel or ramp changes in level	\$20,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$5,000
Objects protrude into accessible route	
Relocate protruding obstacles or widen aisles	\$5,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$30,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Emergency Operations Center	\$24,000
01-Approach & Entrance	
Entrance Main Double Door	
Exterior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$20,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient restroom amenity reach range	
Remount the restroom amenity to allowable reach height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Field Operation/ Maintenance	\$60,000
01-Approach & Entrance	
Entrance	
Exterior Accessible Route	
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$45,000
02-Goods & Services	
Interior	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
West Yard Service Center - Vehicle Services	\$81,000
02-Goods & Services	
Main Entrance	
Reception Counters	
Service counter is not within allowable height/length.	
Remount or replace with ADA compliant service counter	\$20,000
Service counter is not within allowable length.	
Remount or replace with ADA compliant service counter	\$5,000
03-Restroom Facilities	
Restroom - Unisex Single	
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$50,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Wildwood Park	\$25,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Reconfigure accessible route passing spaces	\$5,000
08-Playgrounds	
Play Area	
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Winding Trails Park	\$43,000
01-Approach & Entrance	
Main	
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$25,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$2,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Woofter Family Park	\$229,500
01-Approach & Entrance	
Main	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$40,000
Deficient Curb Ramp Width	
Repair or replace curb ramp to allowable width	\$20,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$6,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$10,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
Lacking proper HC signage/height/content	
Install legible signs at accessible spaces and mount accessible signage at the allowable height range	\$1,500
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$45,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$15,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$15,000
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$5,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$10,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$5,000
Play Areas	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$15,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Bruce Trent Park	\$755,000
01-Approach & Entrance	
Main Entrance	
Curb Ramps	
Deficient Curb Ramp Flares	
Repair or replace curb ramp flares to allowable slope	\$3,000
Deficient Curb Ramp Landing	
Repair or replace curb ramp landing to allowable slope	\$60,000
Exterior curb ramp slope too steep	
Repair, bevel or ramp changes in level	\$3,000
Exterior Accessible Route	
Abrupt surface changes are present	
Repair, bevel or ramp changes in level	\$25,000
Deficient accessible route	
Reconfigure/repair accessible route	\$25,000
Exterior access aisle too steep	
Repair, bevel or ramp changes in level	\$15,000
Parking	
Access aisles obstructed/too narrow	
Relocate protruding obstacles or widen aisles	\$15,000
Access aisles too steep	
Repair, bevel or ramp changes in level	\$20,000
Lacking proper # of HC/Van Access spaces	
Reconfigure/repaint accessible/van accessible spaces	\$5,000
02-Goods & Services	
Park Interior	
Interior Accessible Route	
Deficient accessible route	
Repair, bevel or ramp changes in level	\$100,000
Deficient Walking Slope	
Repair, bevel or ramp changes in level	\$20,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$4,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$7,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$70,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$30,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$4,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Toilet Rooms	
Deficient grab bars	
Obtain and install accessible grab bars	\$7,000
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$2,000
Deficient toilet location	
Remount toilet to allowable centerline range	\$20,000
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$70,000
Grab bar is not within allowable height range	
Remount the handrail within proper height range	\$1,000
04-Additional Access	
Park Amenities	
Drinking Fountains	
Deficient drinking fountain water flow	
Repair or replace drinking fountain with allowable water flow height of 4"	\$5,000
Deficient number of drinking fountains	
Install second accessible drinking fountain	\$15,000
05-Sports Activity Area	
Sports Area	
Sports Activity Areas	
Deficient Access Routes	
Reconfigure/repair accessible route	\$5,000
08-Playgrounds	
Play Area	
Accessible Route Connecting Ground Level Play Components	
Deficient Accessible Route to Ground Components	
Reconfigure accessible route to ground components	\$30,000
Elevated Play Components	
Deficient Elevated Play Components	
Replace/reconfigure/repair elevated play components	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Elevated Play Components Accessible Route	
Deficient Accessible route to Elevated Play Components	
Reconfigure accessible route to elevated components	\$10,000
Ground Level Play Components	
Deficient Ground Level Play Component Configuration	
Reconfigure or replace playground equipment	\$20,000
Ground Surfaces	
Deficient Play Area Ground Surface	
Repair/replace ground surface material	\$10,000
Play Areas	
Deficient Play Area Accessible Entrance/Route	
Reconfigure accessible entrance/route to play area elements	\$30,000
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$40,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Buckskin Basin Park	\$55,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$50,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Centennial Hills Park	\$15,500
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Children's Memorial Park	\$9,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom - Women's Stalls - East	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom - Women's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Craigin Park	\$30,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doc Romeo Park	\$99,500
03-Restroom Facilities	
Restroom - Men's Stalls - North	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Men's Stalls - South	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls - South	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls - North	
Accessible Restroom Stall(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$75,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Single Use Toilet Room(s)	
Deficient toilet stall dimensions	
Reconfigure restroom stall to allowable dimension range	\$15,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Doolittle Park (Kianga Isoke Palacio Complex)	\$12,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom - Women's Stalls - East	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom - Women's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Douglas A. Selby Park	\$6,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Freedom (Gary Reese) Park	\$112,000
03-Restroom Facilities	
Restroom - Men's Stalls - East	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door hardware height	
Replace or remount existing door hardware to the allowable height range	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000
Restroom - Women's - East	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door hardware height	
Replace or remount existing door hardware to the allowable height range	\$1,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$20,000
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$3,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Hadland Park	\$26,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$2,000
Restroom Amenities	
Coat hooks too high	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Remount coat hooks to allowable height range	\$1,000
Deficient maneuverable clearance	
Reconfigure restroom amenities for maneuvering clearance	\$5,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Justice Myron E. Leavitt Family Park	\$30,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Majestic Park	\$20,500
03-Restroom Facilities	
Restroom - Men's Stalls - South	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls - South	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom - Women's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom - Men's Stalls - West	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mike Morgan Family Park	\$46,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	
Repair or replace stall door hardware within allowable height range	\$2,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient door hardware height on restroom stall door	

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Repair or replace stall door hardware within allowable height range	\$2,000
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Stall door lacks pulls on both sides of door	
Repair stall door hardware or replace restroom stall doors	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom Amenities	
Coat hooks too high	
Remount coat hooks to allowable height range	\$1,000
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Deficient sink hardware in restrooms	
Obtain and install proper restroom sink hardware	\$1,000
Mirror edge too high	
Remount mirror to allowable height range	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Mountain Ridge Park	\$8,500
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Deficient Grab bar dimensions	
Remount grab bar to allowable ADA dimensions/height range	\$3,500
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Rafael Rivera Park	\$66,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Deficient front approach to door	
Reconfigure front approach door clearance/relocate sink	\$20,000
Restroom Amenities	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Approach	
Deficient restroom signage	
Obtain and install proper signage	\$3,000
Remount restroom signage to proper height	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Deficient door threshold	
Repair or replace door threshold	\$5,000
Restroom Amenities	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Lacking white protective sleeve	
Insulate exposed pipes	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Teton Trails Park	\$2,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000
Restroom - Women's Stalls	
Restroom Amenities	
Deficient water stream flow time	
Adjust water stream to remain flowing for 10 seconds	\$1,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Thunderbird (Viper) Family Sports Complex	\$22,000
03-Restroom Facilities	
Restroom - Men's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Public Restroom Entrance	
Deficient door clearance	
Reconfigure door clearance	\$10,000
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
08-Playgrounds	
Play Area	
Play Components	
Deficient Ground Maneuvering Clearance	
Reconfigure accessible maneuvering clearance around play area elements	\$10,000

Facility - Affected Area - Barrier - Corrective Action	Corrective Action Construction Cost Estimate
Woofter Park	\$3,000
03-Restroom Facilities	
Restroom - Women's Stalls	
Accessible Restroom Stall(s)	
Stall door is not self closing	
Repair stall door closing function, or replace stall door	\$1,000
Restroom Amenities	
Deficient restroom amenity maneuvering clearance	
Reconfigure restroom amenities for maneuvering clearance	\$1,000
Toilet Rooms	
Deficient restroom amenity reach range	
Relocate restroom amenity to allowable reach range	\$1,000
Grand Total	\$9,976,500